

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

81 05 27

#1L38
ILS-000-001-329**A Person Required to Notify:**

Enter the name and address of the person or organization required to notify.

Name Commander
Street US Army St. Louis Area Support Center
City Granite City State IL Zip Code 62040

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site US Army St. Louis Area Support Center
Street Route 3 & end of Niedringhaus Avenue
City Granite City County Madison State IL Zip Code 62040

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Wright, Larry E., Chief, Installation Management Division
Phone 618-452-4233

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1942 To (Year) 1971 (Deactivation of US Army Depot)

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☒ Solvents
4. ☒ Pesticides
5. ☒ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☒ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☒ Other (Specify)

Radioactive Material

Source of Waste:
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☒ Unknown
18. ☒ Other (Specify)

Miscellaneous operations
as US Army Depot for
29 years.

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000003 MAY 27 81

Form Approved
GSA No. 2000-0138

EPA Region 5 Records Ctr.



357023

MAY 27 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) Miscellaneous land and building storage areas.

Total Facility Waste Amount

cubic feet 4,000,000 C

gallons _____

Total Facility Area

square feet _____

acres 10 A

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☒ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Data is contained in a published installation assessment report prepared by the US Army Toxic and Hazardous Materials Agency. Copies are available upon request to the undersigned.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Data is contained in a published installation assessment report prepared by the US Army Toxic and Hazardous Materials Agency. Copies are available upon request to the undersigned.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other"

Name _____

Street _____

City _____

State _____

Zip Code _____

Signature Chester D. Tutor

Date 20 May 81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☒ Other

CHESTER D. TUTOR
LTC, AGC
Commanding



DEPARTMENT OF THE ARMY
ST. LOUIS AREA SUPPORT CENTER
GRANITE CITY, IL 62040

#1438

STSAS-Z

20 May 1981

U.S. EPA Region 5
Sites Notification
Chicago, IL 60604

MAY 27 1981

Gentlemen:

Please find attached completed Form 8900-1 submitted in accordance with Public Law 96-510, Comprehensive Environmental Response, Compensation and Liability Act of 1980.

Sincerely,

A handwritten signature in cursive script, appearing to read "Chester D. Tutor", is written over the typed name.

CHESTER D. TUTOR
LTC, AGC
Commanding

1 Incl
as stated



UNITED STATES
ENVIRONMENTAL PROTECTION AGENCY
REGION V
111 West Jackson Blvd.
CHICAGO, ILLINOIS 60604

REPLY TO ATTENTION OF:

Date 8-6-81
Reference No. ILS-000-001-329

Dear Superfund Notification Respondent:

The U.S. Environmental Protection Agency (EPA) has received the information you filed pursuant to Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act (Superfund). We are hereby returning this document for the following reason:

- ☒ Essential information is missing or illegible.
Red circles indicate such items.
- ☐ It cannot be determined whether your notification was legally required or whether you were not required to report the site for which you notified.
- ☐ You failed to sign and/or date the document.

Please provide the information requested either on the original document or on the blank form enclosed herein. Return the original document, this letter, and the new form if (necessary) no later than 9-14-81 to:

U.S. EPA, Region V
Sites Notification
111 W. Jackson Blvd.
Chicago, IL 60604

Your notification will be regarded as late if you do not resubmit this information by the above date. If you have any questions on providing this information, please call: (312) 886-6391.

Sincerely yours,

Regional Project Officer



DEPARTMENT OF THE ARMY
ST. LOUIS AREA SUPPORT CENTER
GRANITE CITY, IL 62040

STSAS-Z

11 August 1981

United States Environmental Protection Agency
Region V
111 West Jackson Blvd
Chicago, IL 60604

Gentlemen:

In regard to the attached report information requested, this installation does not have a street number. However, we are located at the end of Niedringhaus Avenue and Illinois Route 3.

I hope this location address is satisfactory. If you require further information, please contact the undersigned at AC (618) 452-4233.

Sincerely,

A handwritten signature in cursive script, reading "Larry E. Wright", is positioned above the typed name.

LARRY E. WRIGHT
Chief, Installation Management Division

1 Incl
as stated

AUG 13 1981

DOD

EPA ID# IL0213820376

SITE NAME U.S. Army St. Louis Center

NORLING FACTOR 18 (>15 PTS.=HIGH MITRE POTENTIAL)

WASTE TYPE

WASTE QUANTITY

(1 ton = $\frac{1}{2}$ cu.yd.=13.5 cu.ft.=4 drums = 220 gals.)

PESTICIDES (5) ✓
HEAVY METALS (5) ✓
PCB's (5) ✓
ORGANICS (4) ✓
SOLVENTS (4) ✓
INORGANICS (3) ✓
ACIDS (3) ✓
BASES (3) ✓
MIXED MUNI-WASTES (2)
UNKNOWN (1) ✓

TONS	CU.YDS.	CU. FT.	DRUMS	GALLONS	PTS.
>875	>437	>11,799	>3500	>192,500	(5) ✓
875	437	11,799	3500	192,500	
251	126	3,402	1001	55,055	(4)
250	125	3,375	1000	55,000	
163	82	2,214	651	35,805	(3)
162	81	2,187	650	35,750	
76	38	1,026	301	16,555	(2)
75	37	999	300	16,500	
21	11	297	81	4,455	(1)
<20	<10	<270	<80	<4,400	(0)

FACILITY TYPE

POPULATION

PILES (5)
DRUMS BELOW GROUND (4) 10,000 or more (5) ✓
DRUMS ABOVE GROUND (3) ✓ 3,000 - 9,999 (4)
SURFACE IMPOUNDMENTS (3) 1,000 - 2,999 (3)
TANKS (3) 101 - 999 (2)
LANDFILLS (2) ✓ 1 - 100 (1)
LAND TREATMENT (2)
UNDERGROUND INJECTION (1)

___ NOT A HAZARDOUS WASTE SITE

___ INFORMATION MISSING

COMMENTS: Releases likely

REVIEWER: C